THE THUM: SCA A & E

1. T. Tally and 1 220 2200

CABRERA GROUP

ARCHITECTS P.C. 134 East 98sh Street New York City 10128 tel 212 417 S880, fee 313 364 6104 rah authoworldsat eti yas

May 9, 2001

The Coalition to Save P.S. 100 152 East 100 Street, Apr. #5E New York, N.Y. 10029

Attention: Ms. Gwen Goodwin, President

Ladies and Gendemen:

At your request, I have reviewed the NYC/BOE Scope of Work for the stabilization of P.S. 100 and visited the site to view the exterior condition of the building as of 07 May '01. Particular attention was given to the remaining terra cotta work at the test duringers.

Our comments are as follows:

1. Scope of Work item No. 4 - Exterior Masonry Dormers

We strongly disagree with the statement. "The stonework at the remaining dorner gables are in various stages of disrepair and in poor condition. This stonework will have to be removed so that the framing of these gobles can be sheathed with pirwood and protected by a new mesibiane to prevent these features from further deterioration "

Post-it* Fax Note

a Alland

Phone 4

Most of the serra cotta "stone work" at the seven dormers on the North (back) sections of the roof appear to be in good (not poor) condition. Only one rear dormer has had most of the T.C. removed. On the adjacent dormer, the upper pieces of one of the vertical pier surround elements are missing but the dormer gable 1.C. work and the other vertical pier are in tact. The terra cona work at the remaining five dormers appear to be usable and in good condition.

- 2. We, therefore disagree with any T.C. removal unless a piece has come long-from its band or unchorage and poses a danger of falling
- 3. Purthermore, in our opinion the individual T.C. "features" have not deteriorated to any great extent over the past century and could continue to be exposed. However it would be necessary to caulk joints where mortar is missing and strap, tie back and secure any potentially loose elements particularly at the partially removed areas.

To conclude, unless the existing glazed terra cotta undergoes a more stringent up-close and through examination which might indicate problems, most of the terra core should be stabilized in place until a restoration project is authorized. Any further removals could cause more harm than good.

Please call if there are ony questions or comments.

Very Truly Yours.

Robert Cabrera

9:\JOSS\VINEK\Freeman work\Q. Goodwin.DOC